

# Evaluation and Repair of Shear Walls of a Parking Garage

Hemant S. Limaye  
Concrete Science, Inc.  
Hayward, CA

# Evaluation and Repair of Shear Walls of a Parking Garage

- Background
- Non-Destructive and Intrusive Testing
- Development of Repair Procedures
- Details of Repairs
- Monitoring of Repairs
- Summary

# Exterior View Terminal A





# Exterior View Terminal B






# Exterior View Terminal B



# Interior View of the Terminal



# **Airport Modernization Plan**

- **Construction of 7-Deck Consolidated Rental Car Facility (ConRAC)**
- **Construction & Renovation of Terminals**
- **\$ 1.4 Billion Design-Build Project Started in 2005 on a Fast-Track Basis**



# ConRAC

- Rental Car Facility Across from the Terminals
- Houses Entire Rental Car Operations & Public Parking Spaces
- 3000 Parking Spaces
- Design: Precast, Pre-stressed Columns and Beams

# Exterior Views of ConRAC





# Exterior Views of ConRAC





# Exterior Views of ConRAC



# Concerns

- 32" Thick Shear Walls Between 1<sup>st</sup> & 2<sup>nd</sup> Floor
- After Removal of Forms Revealed Minor to Severe Honeycombing in some of the Walls
- At a Few Locations Unconsolidated Concrete Extended Through the Entire Depth



# Contractor's Attempt for a Fix





Cement

Sand. Stud



# Contractor's Trade Name



# Group Meeting Recommendation

- Perform Non-Destructive Testing to Determine Extent of the Unconsolidated Concrete
- Develop Repair Procedure(s)





# CSI' s Initial Work-Scope

- Test 10 Walls at  $\sim 150$  Locations Designated by the Engineer of Record Using Impact-Echo (IE) technique
- Locations to Include Honeycombed as well as Sound Concrete

# Impact-echo Principle

- A short pulse is introduced in the structure.
- Reflected waves are analyzed with the waveform analyzer in the frequency domain.
- Dominant frequencies relate to the condition of the structure.






# Impact-echo

- Based on propagation of a stress wave through the material.
- Needs an access from only one side to conduct the tests.
- “Local” Test
- On-site Evaluation- most often no further analysis is needed.

# Plan View





# Overall View




# Overall View





# Typical Shear Wall



# Shear Wall-Side View





# Boundary Elements: Heavily Reinforced























# Honeycombed Concrete















# Conducting IE Tests






# Conducting IE Tests




# IE Results- Sound Concrete






# IE Results-Honeycombed Concrete




# Verification of Test Results





# Verification of Test Results





# Verification of Test Results





# Results Summary

- Majority of the Locations Did Not Contain Through the Depth Voids
- A Few Locations Contained Unconsolidated Concrete up to 40% of the Depth

# Results Summary

**ONE EXCEPTION**





# Shear Wall IE Results

- Showed Inconsistent, Non-Repeatable Signals at Two Adjacent Locations



# Shear Wall- Add' L Work

- Chipping of the Concrete Showed Color Variation





# Shear Wall- More Add' L Work

- Drilled and Removed Partial Depth, 2" dia. Cores Close to the Interior Rebar









....And then Drilled 5/8" Dia. Holes





# For Borescope Observations





# Borescope Observations Showed

- Interior Delamination
- Bug Holes in One Hole, Depth: 8-9"
- Crack in Another Hole; Depth: 9-10", Color Change in Material
- Crack in Third Hole; Depth: ~8", Color Change in Material Starting at 6.5"

# Recommendations

- Perform Microscopic Examination to Characterize the Concrete
- Chip the Area Concrete to Examine the Interior Condition



Chipping of  
unsound concrete







Large chunks came out easily





Significant delamination at  
the rebar depth

# Development of Repair Procedures

- With the Discussions Between the Engineer, Material Supplier & CSI, Repair Procedures Were Developed for Three Different Conditions Using ACI & ICRI Guidelines:
- No.1: For Defects up to 1½" Deep
- No.2: For Defects More than 1½" Deep & Rebars Are Exposed in Non-Boundary Elements



# Development of Repair Procedures for Various Conditions

- No. 1: For Defects up to 1½" Deep, Minimum Rebar Exposure
- No. 2: For Defects More than 1½" Deep & Rebars Exposed in Non-Boundary Elements
- No. 3: For Defects More than 1½" Deep & Rebars Exposed in Boundary Elements

# General Repair Details

- Saw-Cut Straight Edges,  $\frac{1}{4}$ " Deep, No Feathering
- Mechanically Remove All Honeycombed Concrete with a Fractured Aggregate Profile  $\sim \frac{1}{4}$ "
- Presoak Concrete Surface to Provide SSD Condition
- Mix & Apply the Repair Material
- Damp Cure for 3 Days



# Differences in Procedures

- Procedure 1: Different Material for Shallow Repairs
- Procedures 2 & 3: Same Material but in Procedure 3, Repair Material to be Placed by Forming & Pumping.

# Hammer Sounding





# Saw Cutting the Outer Edges





# Chipping the Concrete





# Checking the Profile



# Offering Guidance





# More Chipping!





# Cleaning





# Cleaning





# Water Supply





# Spraying with Water





# Spraying with Water





# Checking the Depth





# Checking the Depth





# Good Chipping Work!

Condition 2






# Good Chipping Work!



Condition 3



# Condition 3 Repair Details




Caulking



# Forming







Completed Formwork with Braces






Completed Formwork- Another View





Clamps to hold the forms securely






**Inlet Nozzle**





**Inlet Nozzle**





Ventilation Holes



Achieved the SSD Condition for the Concrete by Flooding the Formed Area with Water and Emptying it.

Procedure also served to make sure that the forms were sealed properly.



Getting Ready to Mix the Material















## Brand New Pump







Had to get used to  
the new pump!






**Faced a few challenges with leakages  
and bulging forms**








Indication that the repair material has reached the level at the ventilation hole




Date: 8-15-00 YH Page No. 1  
 Project: Airport  
 Rental Car Parking Structure




Concrete Science Inc.  
 Materials & Structural Engineers  
 Tel. (510) 581-2342  
 Fax. (510) 581-4178

# Shear Wall No. 7 East



\* Area #3B continues onto South face of wall, connects to Area #4 on South. Needs more chipping done tomorrow.  
 Area #2 chipped to a total depth of 7 1/2" at ground level on South side.


## Area #13



▨ = rebar exposed    ▩ = top surface only removed  
 Area #3B

	A	B	C	D
Horiz. rebar thickness	5/8"	5/8"	5/8"	5/8"
Horiz. rebar depth	2"	2"	2"	2"
Vert. rebar thickness	5/8"	N/A	5/8"	5/8"
Vert. rebar depth	3"	N/A	2 1/4" - 3"	2 3/4" - 3 1/4"
Chipping depth	2" - 12 1/2"	4"	2" - 5"	4" - 6"


Horiz. rebar thickness = 5/8"  
 Horiz. rebar depth = 2"  
 Chipping depth = 3 1/2" - 4 1/2"



Documentation




Date: 8-26-08 Page No. 2  
 Project: Airport  
 Rental Car Parking Structure




Concrete Science Inc.  
 Materials & Structural Engineers  
 Tel. (510) 581-2342  
 Fax. (510) 581-4178

Shear Wall No. 18 South



8-22: hollow sounding sections of wall fell away in large chunks - up to 15" x 6" and 2" thick!  
 8-25: sample of concrete at approx. 3" depth taken (marked with X - 63" from West face and 17" from bottom perimeter of section)  
 8-27: rebar ties cut off





Horiz. rebar thickness = 5/8"  
 Horiz. rebar depth = 2"-2 1/2"  
 Vert. rebar thickness = barich  
 Vert. rebar depth = 3"  
 Chipping depth = 1"-4 1/2"

on 8-26-08 all three core holes were chipped out to their max depths:  
 Core #1 = 10"  
 Core #2 = 12"  
 Core #3 = 9"

Documentation

# Paper Work

<p>Date: _____ Page No. _____</p> <p>Project: <u>San Jose Airport</u> <u>Rental Car Parking Structure</u></p>	<div style="text-align: center;"> <b>Concrete Science Inc.</b> Materials &amp; Structural Engineers</div> <p>Tel. (510) 581-2342 Fax. (510) 581-4178</p>
<div style="display: flex; justify-content: space-between;"><div>Shear Wall No. _____</div><div>Repair Area No. _____</div></div> <div style="text-align: center; margin: 20px 0;"></div> <div style="display: flex; justify-content: space-between;"><div>Type of Repair: _____</div><div>Material Used: _____</div></div> <div style="display: flex; justify-content: space-between;"><div>Temperature: _____</div><div>Relative Humidity: _____</div><div>Wind: _____</div></div> <div style="display: flex; justify-content: space-between;"><div>Amount of Mixing Water: _____</div><div>Amount of Material: _____</div></div> <div style="display: flex; justify-content: space-between;"><div>Time/Mixing Start: _____</div><div>Mixing Time: _____</div><div>Time/Application: _____</div></div> <div>Surface Condition: _____</div> <div>Notes: _____ _____ _____ _____ _____ _____ _____ _____</div>	





## Repair Summary Table

[illegible]

# Condition 3: Finished Repair





# Condition 3: Finished Repair



# Curing Procedure

- For Conditions 1 & 2: Application of Water Based, Film Forming Curing Compound
- For Condition 3: Form Curing for 3 Days and then Application of the Curing Compound



**Chipped  
Areas**



**Repaired  
Areas**





Before



Partially  
Finished





Before



Partially  
Completed



# Summary

- Honeycombed Shear Walls Were Tested with Impact-Echo.
- IE Results Indicated that at Some Locations Unconsolidated Concrete Extended up to 13-14" from the Surface.
- Repairs Were Completed with Three Procedures.
- Successful Completion with Cooperation from Everyone Involved in the Project.



# Thank You !

*Any Questions?*