

UNUSUAL PROJECTS



2025SPRING CONVENTION

AUSTIN, TEXAS • APRIL 13 – 16, 2025

www.icri.org



UNCOMMON CONCRETE SWIMMING POOL REPAIRS

Dunja Vla Associate Principal



www.icri.org









2025 SPRING CONVENTION APRIL 13- 16, 2025

WHAT POOLS HAVE IN COMMON? MAKE PEOPLE HAPPY

WHICH PROBLEM CONCRETE POOLS HAVE IN COMMON? LEAK

WHICH POOLS ARE BEST?

THE ONES WHERE YOU ARE THEGUEST!

You come and leave and let other people worry about it











WHAT IS UNIQUE ABOUT POOL STRUCTURES?

- Constantly exposed to harsh environment
 - Chemically treated water
 - High humidity in natatoriums
- If not inground, space below them is typically occupied and used as
 - Storage space
 - Parking
 - Office space
- When they leak it affects the space below them
- When they leak it costs a significant amount of money to keep the water level
- Short period of time when they can be repaired. Typically, during swimming competion season breaks or short time closures for basic maintenance



WHAT IS TYPICAL DISTRESS?

- Cracked and debonded tiles
- Cracked and debonded plaster
- Breached liners
- Breached waterproofing membrane
- Concrete delaminations /spalls
- Corrosion of metals
- Clogged drains / leaking drains
- Sealant debonded / deteriorated / stained
- Damaged grates at gutters, bulkheads and drains
- Bulkheads deteriorated bearings
- Corroded / broken duct supports at the ceiling of indoor pools



FOCUS OF THIS PRESENTATION

Four different projects will be presenting with some uncommon concrete swimming pool repairs such as:

- Repair of expansion joint
- Repair of leaching butyl -rubber waterstop through construction joints
- Repair of pool deck in area above chlorine storage and embedded high voltage corroded conduits in it
- Repair of pool deck supported by steel framing





Project No. 1 - Pool with Expansion Joint in Walls and Floor Slab



lssues

- opening
- opening

Pool started losing water immediately after

• Black gooey-like material (waterstop residue) started leaching through pool walls and inside the gutter at several locations after one year of

Live Content Slide

When playing as a slideshow, this slide will display live content

Poll: Have you ever seen an expansion joint inside a pool?





Expansion Joint in Floor Slab



Pool slab



As built joint

Expansion joint in pool floor slab

Testing of Expansion Joint



During dye testing the following was discovered:

- **1. Expansion joint was leaking at the gutter level**
- 2. Expansion joint leaks down the side of the pool walls as well as across the floor slab

Repair of Expansion Joint

Expansion joint at pool floor and walls

Repaired joint prior to installation of polysulfide sealant

Repair of Leaching Waterstop at Joints

Leaching residue from

black waterstop

Cementitious coating installed over urethane waterproofing membrane with full sand refusal Quarts plaster finish installed over urethane waterproofing membrane with full sand refusal

At pool stairs

Project No.2 - Pool Deck Area Over Chlorine Storage and Filtration Tanks

BEFORE REPAIRS

OLYMPIC SIZE POOL– BUILT IN 1985

DURING REPAIRS

Area of chlorine storage and filtration tanks below the deck

POOL DECK - CONCRETE TOPPING OVER STRUCTURAL SLAB

Delamination Survey

TOP OF THE DECK SLAB

Area of chlorine storage and filtration tanks below the deck

Concrete exposed to chlorine evaporation is significantly more prone to deterioration

UNDERSIDE OF THE DECK SLAB

Scope of Repair Work

At Pool Deck

- Replace delaminated concrete topping with ceramic tile finish at all four pool decks
- Repair delaminated concrete slab, top and underside. Full depth repairs were expected at select areas
- Waterproof pool deck
- Replace all linear deck drains

Inside Pool

- Infill two underwater pool windows
- Repair debonded tiles at pool walls and bottom
- Replace sealant around gutters
- Duration of project: 2 months (July August, opening on Labor Day)

Unforeseen Issue

UNDERSIDE OF THE DECK SLAB DELAMINATION AND WALLS SURVEY

Structural Slab Repairs Extended Beyond Projected

Impact on Project

- Embedded 480 V conduits needed to be removed from the slab
- The rest of the electric grid was affected by this too and needed to be repositioned
- This required revision of the project phasing and shoring of equipment around filtration tanks
- Added significant cost to the project, over \$2M
- Significantly affected duration of the project

Chlorine storage and filtration tanks room below the deck – overall view

Deck underside during repairs

o d to be repositioned ipment around filtration tanks

Project No. 3 - Leaking Inground Outdoor Pool (50 years old)

Issues that prompted investigation:

Client wanted answers to two questions:

- Can the leaks be fixed?

 Pool has been leaking for years Cracks were repaired numerous times. The last repairs were done 2 years prior to our investigation Poor workmanship of those repairs

• Can the useful life of the pool be extended by 15 years after repairs with minimal maintenance?

Past Repairs

Repaired crack (typ.)

Paint from concrete shell was not fully removed

Photo taken by the client during past repair, prior to installation of cementitious coating

White cementitious coating

Grey cementitious coating

Cementitious coating finish

Investigation to Determine As -Built Conditions

GPR scan of slab and walls

Taking concrete cores

All pool walls and slab were sounded with hammer and chain drag

Getting soil samples with hand auger

Concrete Samples

Typical cracks observed in the deep end of the floor

Shallow end – 6" thick floor slab

Deep end- 3" thick floor slab

Shallow end floor – 6" thick slab

Reinforcing mesh was observed at the bottom of the concrete slab

No cores were done at walls. By sounding, only minor deterioration was detected around pool lights

Repairs of Pool Walls

Removal of old paint and cementitious coatings in progress

One to two inches of concrete on walls were soft and crumbling

Wall Repair Options - Mockups

Mockups of various depth removal, repair expectations and final finish

Crack Repairs

Cracks were repaired at shallow and deep end of the pool

Crack repair detail

Completed Repairs

Condition of the pool at the end of repairs

Condition of the pool two years after the repairs

No leaks were reported

Project No. 4 - Partially Elevated Pool Deck Supported by Steel Beams

Overall view of the pool and the pool deck

View of the pool enclosure (south elevation)

Pool deck level – plan view

Basement level - plan view

Structural Framing - Section

Cross section through the pool building, north-south direction

Client's Concern

Upward displacement of the south deck along expansion joint

Top of the Pool Deck Slab

Sound concrete underneath sheet membrane

Expansion joint below sheet membrane

Exposed expansion joint

Upward Displacement of South Pool Deck

Top View

Upward displacement of the South pool deck (1 ¹/₄ inch) – South deck

Underside View nch) – South deck

Underside of the Pool Deck – Corroded Beam Tops and Column Base Plates

Area of concrete repaired in the past was sound

Corrosion present at the top flange

- Corrosion built up causing jacking of the structure above

Section loss at the base of the column

Delamination on Underside of the Pool Deck – North and East End

Expansion joint above

Concrete encasement around steel columns – part of past repairs

Along the pool edge / expansion joint

Above the chlorine tanks

Corroded Steel Beam Ends and Post Bases at North Deck

Corroded beam end (north deck)

Corroded post base (north deck)

1" wide gap between slab and beam

Summary of Delamination Survey

Delamination survey on the underside of the pool deck

Legend: Delaminated concrete on the underside of the pool deck

- Upward displacement of the pool deck
- -- Steel beams

Extent of Deck Repairs in Area Above Chlorine Tanks

Underside of deck prior to concrete removal

Full depth repairs

Repairs at Steel Beams

Repairs Below Deck

Detached drains were discharging water from the west deck on the walls below it

- Corroded base plates that were jacking south concrete deck were replaced with new

Completed Repairs

Raised edge of the jacked slab was grinded down

Replacement of pool liner was added as change order and is ongoing

Conclusions

- Although concrete pools on first glance appear to fit the category "if you've seen one, then you've seen them all," each of them have unique design features, regarding both pool deck s and pool shells, and failure modes that require thinking -outside-the-box repair approach
- Do not assume that the condition of pool slab is the same as the condition of walls
- It is always wise to add a few extra exploratory openings during the investigation phase
- If asked by the client to focus only on deck, as a minimum glance at the pool as well and point at issues if you see them and follow up in writing
- Test drains during the investigation phase
- Restoration of pools are interesting and rewarding projects, as the difference before and after conditions is typically significant

SESSIONEVALUATION

Resources	
Evaluate this Session	\bigcirc

To complete the session evaluation, open the ICRI Convention App.

Under **Plan Your Event**, select Schedule, and then the Technical Session you are attending. Select the subsession you are attending, scroll down to Resources, and select Evaluate this Session.

www.icri.org

2025 SPRING **CONVENTION** APRIL 13-16, 2025

THANK YOU

Dunja Vla Associate Principal Wiss, Janney, Elstner Associates, Inc.

www.icri.org

2025 SPRING CONVENTION APRIL 13 – 16, 2025

ANY QUESTIONS?

www.icri.org

2025 SPRING CONVENTION APRIL 13- 16, 2025