



2025 **SPRING CONVENTION**

AUSTIN, TEXAS • APRIL 13 – 16, 2025

www.icri.org



REHABILITATION OF HERITAGE BUILDINGS

Presenter: Mohamed Anber

Title: Project Manager

Company: Kabbani Construction Group

CONTENTS

CONTENTS

INTRODUCTION

BUILDING SYSTEM

3D LASERSCANNING

BUILDING MATERIALS

GUIDELINES & STANDARDS

BUILDING STATUS (before rehabilitation)

REHABILITATION WORKS

QUESTIONS



INTRODUCTION

- Al Balad is an exceptional urban and historical fabric which is an essential part of Jeddah's identity. Jeddah is the second city of Saudi Arabia located on the Red Sea. It is the main seaport of contemporary Saudi. Jeddah is part of the Hejaz region composed by the strip of land between the Red Sea and the mountains, which are also part of the region
- Jeddah is characterized by a distinctive architectural tradition composed of tower houses built in the late 20th century by the city's mercantile elites. Jeddah's proximity to the red sea combines the local extraction of the renowned coral stone with contemporary influences and crafts from the trade routes. The combination brought forth a very unique and characterizing type of architecture and construction methods




INTRODUCTION

CASE STUDY (BAIT ALSIRAFI BUILDING)

- The building is located at Haret Al Sham, west - south of Al Baiaa Square at Jeddah city
- It consists of four stories, with total built up area of 1367 m². The building system consists of coral stones for walls and structural wooden beams for slabs
- The building was constructed as a residential building. Based on the architectural design and historical conclusions, the building was inhabited by two different families

بيت الصيرفي



Live Content Slide

When playing as a slideshow, this slide will display live content

Poll: Using natural raw materials found in the surrounding environment instead of materials such as concrete or steel may be more economically and environmentally friendly for building residential buildings.

BUILDING SYSTEM

Foundations :


Coral (Manqabi) stone

Bearing walls:

Coral stone + wooden beams (Takalel)

Slabs:


Structural wooden beams + cladding +
top reinforced concrete slabs



BUILDING SYSTEM



Third floor + roof
Area = 219.66 m²



Second floor + Mezzanine
Area = 342.62 m²



First floor + Mezzanine
Area = 425.97 m²



Ground floor + Mezzanine
Area = 379.14 m²

3D LASER SCANNING

North & East elevations



North & West elevations



South & East elevations



South & West elevations



BUILDING MATERIALS



CORAL STONE



MORTAR



STRUCTURAL ELEMENT
(BEAMS, JOISTS)


GUIDELINES & STANDARDS

- Survey & Inspection
- Structural behavior assessment
- Evaluation
- Rehabilitation recommendations



BUILDING STATUS(before rehabilitation)

- Ground water table exists at 1.20 m below ground level
- Decay of many coral stone bearing walls
- Third floor and roof walls were built with irregular shape coral stones
- NHL plaster at most of coral stone walls was found in deteriorated condition
- Structural wooden beams at walls (Takalel) deterioration condition vary from medium (need restoration) to severe (need replacement)
- Structural slabs wooden beams deterioration condition vary from medium to severe
- Architectural wooden elements condition vary between missing elements, medium damage elements (need restoration), and severe damage elements (need replacement)



REHABILITATION WORKS

Work steps

- Site housekeeping and pest control
- Documentation and coding
- Temporary supporting installation
- Tests
- Critical cracks stitching at walls
- Replacement of deteriorated walls coral stones, from ground floor to roof
- Restoration / Replacement of structural wooden elements at slabs from roof to ground floor
- Resisting building slope by using reinforcement bars and galvanized steel plates at concrete slabs
- Insulation of roof slab
- Strengthening of foundations
- Plastering with NHL material (Natural Hydraulic Lime)
- Restoration / Replacement of architectural wooden elements
- Restoration of gypsum decorative elements



REHABILITATION WORKS

Housekeeping and pest control

- Removal of all wastes
- Pest control



REHABILITATION WORKS

Documentation and coding


- Numbering each room / void
- Photograph each room / void
- Preparation of documentation report



REHABILITATION WORKS

Temporary supporting installation

- External supporting with steel sections
- Internal supporting with Propping



REHABILITATION WORKS

Tests

- Soil investigation
- Masonry test
- Structural wood test
- Architectural wood test



REHABILITATION WORKS

Tests

Minimum acceptable range of material properties to be used in restoration

Stone		
Property	min	max
Absorption (%)	N/A	20
Specific Gravity (bulk oven dry (-))	1.40	1.98
Compressive Strength (Mpa)	5.08	N/A

Wooden Beams			
Property	Wood type	min	max
Dry Density (kg/m ³)	Juniperus (Arar)	900	1200
	Mahogany	500	1100
Compressive Strength (Mpa) Parallel to Fiber	Juniperus (Arar)	40	N/A
	Mahogany	40	N/A
Compressive Strength (Mpa) Across the Fiber	Juniperus (Arar)	20	N/A
	Mahogany	20	N/A
Flexural Strength - Modulus of Rupture (Mpa)	Juniperus (Arar)	79	N/A
	Mahogany	79	N/A

	Windows					
	Natural Density (kg/m3)	Flexural Strength - Modulus of Rupture (Mpa)	Parallel to Fiber		Accross to Fiber	
			Compressiv e Strength (Mpa)	Young's Modulus (Mpa)	Compressive Strength (Mpa)	Young's Modulus (Mpa)
Not Less than	350	5.5	3.6	95	2.2	8.9
Accepted Average	530	30.8	13.0	633	4.1	89.0

	Roshans					
	Natural Density (kg/m3)	Flexural Strength - Modulus of Rupture (Mpa)	Parallel to Fiber		Accross to Fiber	
			Compressiv e Strength (Mpa)	Young's Modulus (Mpa)	Compressive Strength (Mpa)	Young's Modulus (Mpa)
Not Less than	385	20	3.3	103	2.9	95
Accepted Average	697	35.5	14.3	808	4.8	354

REHABILITATION WORKS

Critical cracks stitching at walls

- Inspection of all the building cracks
- Stitching the critical cracks
- Installation of gypsum stickers at cracks locations
- Installation of cracks meters (rulers) at cracks locations



REHABILITATION WORKS

Replacement of deteriorated walls coral stones, from ground floor to roof

- Restoration of partially damaged coral stones
- Replacement of totally damaged coral stones
- Building new coral stone walls (where required)
- Removal of existing coral stone walls (where required)
- Restoration / Replacement of wooden Takalel



REHABILITATION WORKS

Restoration / Replacement of structural wooden elements at slabs from roof to ground floor


- Demolition and removal of existing RC slabs above wooden beams
- Restoration of semi damaged wooden beams
- Replacement of damaged wooden beams with new ones of same shape and section
- Installation of cladding



REHABILITATION WORKS

Resisting building slope by using reinforcement bars and galvanized steel plates at concrete slabs

- Building slope status
- Survey monitoring of the slope



REHABILITATION WORKS

Resisting building slope by using reinforcement bars and galvanized steel plates at concrete slabs

- Installation of additional reinforcement steel bars at slabs, that are welded with the slab reinforcement steel bars, and extending in the coral stone walls to outside
- Installation of galvanized steel plates (10 cm width, 1 cm thickness) connecting the reinforcement steel bars from outside, to stabilize the building slope at all floors



REHABILITATION WORKS

Insulation of roof slab

- Waterproofing insulation
- Heat insulation
- Screed casting



REHABILITATION WORKS

Strengthening of foundations

- Excavation
- Dewatering
- Replacement of deteriorated coral stones
- Casting plain concrete
- Strengthening (increasing the existing foundations width), as per structural study recommendations
- Termite control
- Backfilling
- Casting RC slab on grade



REHABILITATION WORKS

Plastering with NHL material (Natural Hydraulic Lime)

- 1st and 2nd layers, before foundations strengthening
- 3rd layer (finishing), after foundations strengthening and installation of architectural wooden elements



REHABILITATION WORKS

Restoration / Replacement of architectural wooden elements

- Restoration of partially deteriorated elements
- Replacement (fabrication) of missing or fully deteriorated elements



REHABILITATION WORKS


Restoration of gypsum decorative elements

- Restoration of partially deteriorated elements
- Casting similar molds for fully deteriorated elements





REHABILITATION WORKS





SESSION EVALUATION

Resources

Evaluate this Session



To complete the session evaluation, open the ICRI Convention App.

Under **Plan Your Event**, select Schedule, and then the Technical Session you are attending. Select the sub-session you are attending, scroll down to Resources, and select Evaluate this Session.



ANY QUESTIONS?

www.icri.org

2025 SPRING
CONVENTION
APRIL 13- 16, 2025