

The background of the left side of the image is a photograph of the Austin skyline, featuring several tall skyscrapers. In the foreground, there is a concrete wall and a paved area. On the paved area, there are several concrete repair projects, including a large star-shaped patch with the word "AUSTIN" and a star inside it, and another patch with the word "BRAVADO" and "250 MILES".

Keep Concrete Weird

UNUSUAL PROJECTS



2025 **SPRING CONVENTION**

AUSTIN, TEXAS • APRIL 13 – 16, 2025

www.icri.org



De-Mystifying Unusual Results on Extraordinary Structures - Case Studies of Concrete Challenges

Gina Crevello

Principal

Echem Consultants LLC

Paul Noyce

Chief Technical Officer

Echem Consultants LLC

1-14 pmofk c
1 ks akqfl k
] mof /2 Ö/5e1-14

1-14 pmofk c
1 ks akqfl k
] mof /2 Ö/5e1-14

AGENDA

- k ä è xÜ _ ä â {ç} è } É a â ê xÜ
- k ä è xÜ m ç ä z Ü à é xç } a â ê xÜ
- Standards for Testing
- Limitations in Testing
- Case Studies Interpreting Results



NOT ALL CONCRETE IS EQUAL

NOT ALL CONCRETE IS EQUAL

- Architectural and sculptural concrete may have similar or common construction materials – but their significance may be much greater than the average concrete structure





NOT ALL CONCRETE IS EQUAL

- Or they may have little in common with traditional reinforced concrete creating challenges in assessing existing conditions and analyzing test data



NOT ALL CONCRETE IS EQUAL

- Significance and function may change with time or events

NOT ALL CONCRETE IS EQUAL

• ` } è } ç ã ç x è ã â à } { Ç x â É à é
à x î Ç x ë } x Å ç } x è } ç } ♥ } { è ä â
x ç { Ç É } { è ç x Ü x â | é { ê ã è ç x Ü ê }
ë ä ~ ê â { è ã â è x } é è Ç } è É é è x â |
ë x ã } é x é é ä { É x è } | í É Ç è Ç }
é è ç ê { è ç }





NOT ALL CONCRETE IS EQUAL

- Differences in construction materials
 - Aggregate
 - Reinforcing
 - Surface treatments

NOT ALL CONCRETE IS EQUAL

Differences in surface treatments





NOT ALL CONCRETE IS EQUAL

- Differences in repair
PHILOSOPHY and methodology

NOT ALL PROBLEMS ARE EQUAL

pè} } Ümçäz Üÿà é s } çéêé _ äâ {ç} è} mçäz Üÿà é





**NOT ALL PROBLEMS ARE
EQUAL**

STEEL PROBLEMS

CORROSION IN CONCRETE – THE BASICS

Reinforcing Steel Corrosion exists when you have one or a number of the following Conditions

1. Exposure to the atmosphere (via cracks)
2. The pH of the concrete has dropped below 10
3. Chlorides are present on the steel surface




Figure 1. Thermodynamic stability of iron in aqueous solution after Pourbaix. (Right: Corrosion, immunity and passivation diagram for iron by A. Pirson [ii])

NOT ALL PROBLEMS
ARE EQUAL

CONCRETE
PROBLEMS



ALKALI SILICA REACTION (ASR) – THE BASICS

] p o } i É œ í Ç } â î ä ê Ç x ë } ä â } ä ç x â ê à z } ç ä ~ è Ç } ~ ä Ü í Í Å _ ä â | É Ä â é

/ E o } x { œ } p É x] Å Å ç } Å x è }

1 E p ê ' { É â è] Ü x Ü

2 E p ê ' { É â è j ä É œ ç }

1 k a] bba_ qp qe a l qe a o

a ì ã ä é ê ç } ë ä ò Ç }] è à ä é ã Ç } ç }

- _ ä â { ç } è } x { è è x é x ã ç ä è } { è é } z x ç ç È } ç ä ä } â ë È ç ä â à } â è x Ü } ì ã ä é ê ç }
- t x è } ç
- l ì î Å } â
- { Ç } à È x Ü
- t Ç } â { ä â { ç } è } { ç x { Ö é È ç } à ä ë } é è Ç È ä ç ä è } { è é } z x ç ç È } ç





t e] q p q] k ` ] o ` p] o a q e a o a b l o q a p q f k c

Non-Destructive Standards:

USA Standards include:

AMPP (NACE) SP308 2018 "Inspection Methods for Corrosion Evaluation of Conventionally Reinforced Concrete Structures"

ACI 228.2R-13- "Report on Nondestructive Test Methods for Evaluation of Concrete in Structures"

ACI PRG228.4-23 - "Visual Condition Survey of Concrete—Guide"

International Atomic Energy Agency (IAEA): Guidebook on Non-Destructive Testing of Concrete Structures

International Standards include:

ISO 16312:2024 - "Maintenance and repair of concrete structures —Part 2: Assessment of existing concrete structures"

ISO 19207:2004 - "Testing of concrete —Part 7: Non-destructive tests on hardened concrete"

ISO 13822:2010- "Bases for design of structures —Assessment of existing structures"

European Standards are:

RILEM TC 154-EMC "Electrochemical techniques for measuring metallic corrosion in concrete"

EN 125042:2012- "Testing concrete in structures—Part 2: Non-destructive testing —Determination of rebound number"

EN 125044:2004 - "Testing concrete —Part 4: Determination of ultrasonic pulse velocity"

t e] q p q] k ` ] o ` p] o a q e a o a b l o q a p q f k c

- Non-Destructive Testing Example Standard such as:

- **AMPP (NACE) SP308-2018 Section 3:**

- (a) Visual inspection techniques;
- (b) Crack inspection;
- (c) Delamination survey;
- (d) Cover thickness survey and reinforcement location;
- (e) Assessment of concrete strength and condition; *Invasive*
- (f) Corrosion potential measurements; *Invasive*
- (g) Corrosion rate measurement; *Invasive*
- (h) Carbonation depth measurement; *Invasive*
- (i) Concrete resistivity measurement;
- (j) Electrical continuity testing of reinforcement; *Invasive*
- (k) Chloride content measurement and chloride profile determination in the concrete; and *Invasive*
- (l) Other advanced techniques

- **AMPP (NACE) SP308-2018 Section 4:**

4.2 Environmental Factors:

“A number of environmental factors should be considered when a corrosion survey is performed. Descriptions of some of the most important factors follow. Some indication as to their effects on design or feasibility of restoration methods is given.”

- Temperature & Humidity
- Precipitation
- Load Factors

t e] q p q] k ` ] o ` p] o a q e a o a b l o q a p q f k c

_ x â í }] â é í } ç è Ç } b ä Ü ä í Í Ä Å Æ

e ä í j ê { Ç q } é é Ä Å | ä í } k } } | ê

e ä í | ä í } é } Ü { è í Ç Ç Ç è } é è x â | í Ç x è à } è Ç ä | é ê

t Ç x è x ç } í } Ü ä Ö Ä Å ~ ä ç è

e ä í | ä í } } ë x Ü x è } è Ç } | x è x è

t Ç x è | ä } é è Ç } ~ ê è ç } Ü ä Ö Ü } è

t Ç ä à x Ö } é è Ç } | } { É Ä ä é ê




CORROSION ANALYSIS

- Corrosion Potential and activity

1. Half-cell potential (HCP) measurement (E_{corr}) & mapping

ASTM C876

Potential (mV) w.r.t. CSE	Probability of Corrosion Activity (%)
> -200	10
-200 to -350	Uncertain
<-350	90



CORROSION ANALYSIS

- Corrosion Potential and activity analysis in the field*




- 1. HCP gradient
- 2. Corrosion current density (i_{corr})
- 3. Corrosion Index (CI) Category

of i a j q _ 3 4 3 Q a j _ e x U _ } U U

Table 1 - Typical ranges of potentials of normal steel in concrete (Volts CSE)	
water saturated concrete without oxygen	-0.9 -1.0 V
wet, chloride contaminated concrete	-0.4 -0.6 V
humid, chloride free concrete	+0.1 -0.2 V
humid, carbonated concrete	+0.1 -0.4 V
dry, carbonated concrete	+0.2 0 V
dry concrete	+0.2 0 V


of i a j q _ 3 4 3 Q a j _ _ ä ç ä é É â o x è } é

i_{corr} ($\mu A/cm^2$)	Corrosion Level
≤ 0.1	Negligible
0.1 - 0.5	Low
0.5 - 1	Moderate
>1	High



Condition Index (CI) Category


CI Category	Corrosion condition	Corrosion Measurement
0	Good	$-200 < E_{\text{corr}}$ and $0 < I_{\text{corr}} < 0.1$
1	Fair	$-200 > E_{\text{corr}} > -350$ or $0.1 < I_{\text{corr}} < 0.5$
2	Poor	$-350 > E_{\text{corr}} > -500$ or $0.5 < I_{\text{corr}} < 1$
3	Severe	$E_{\text{corr}} < -500$ and $1 < I_{\text{corr}}$





LIMITATIONS

- **Challenges with Assessments**
 - Access
 - Sample size
 - Treatments
 - Permanent Coatings



LIMITATIONS

- Access



LIMITATIONS

- $_ \zeta x \Psi \hat{A} \}$ é í $\acute{E} \zeta]$ éé} ééà } â èé
- $] \{ \{ \} \}$ ééépxà ã $\ddot{U}$ p $\acute{E} \}$ é1 z éèçê {è $\acute{E} \hat{a}$ éémê z $\ddot{U}$ p ã x { } é

LIMITATIONS

- Limitations in sample size often dictates supporting laboratory analysis
- In some instances, only spalled concrete can be tested





CASE STUDIES


www.icri.org

1-14 pmofk c
1 ksakqfl k
]mofi /2 Ö/5e1-14



Pavilion on the pond New Canaan, Connecticut

- ❑ 1962, Philip Johnson's folly at home estate "Glass House"
- ❑ Pre-cast 'Shockbeton' system
- ❑ Historic Landmark
- ❑ Precursor to Lincoln Center




l k p q o r q f l k q v m l i l c v


m s f i f l k l k q e a




CURB CONDITIONS


PAVILLION ON THE









Corrosion Rate Map
($\mu\text{m}/\text{yr}$)




Potential Map (mV)






Corrosion Rate Map
($\mu\text{m/yr}$)



Potential Map (mV)



o } éê ľě xè _ ä ľě à â Ě

	Potential (mV) w.r.t. Ag/AgKCl	Corrosion Rate (µm/yr ⁻¹)	Section Loss (mpy)
Minimum	0.1	0.15	0.00591
Maximum	-290.9	7.82	0.308108
Average	-113.2	1.16	0.045838

o } éê ľě xè _ ê çz Ě

	Potential (mV) w.r.t. Ag/AgKCl	Corrosion Rate (µm/yr ⁻¹)	Section Loss (mpy)
Minimum	-180	0.34	0.0134
Maximum	-300	2.81	0.1107
Average	-244	1.48	0.0583



Pavilion on the pond

Results

- ❑ Carbonated pre-cast structure
- ❑ Corrosion is a result of carbonated concrete
- ❑ Potential was largely influenced by moisture- seen at the base of the column
- ❑ Without the use of LPR Testing, corrosion hot spots would not have been identified.




Irish Hunger Memorial New York, New York

- ❑ 2002, designed collaboratively by artist Brian Toll, landscape architect Gail Wittwer-Laird and architecture firm 1100 Architect.
- ❑ Designed to resemble a hill in the Irish countryside
- ❑ Concrete structure with epoxy coated rebar










_ ä ç ç ä é Ĥ â o x è } é í Ĥ Ç 3 ë x ç Ĥ è Ĥ â é ä ~ é ê ç x { }
} ï ã ä é } | é è } } Ü x ç } x é Ĥ
ă ä Ũ ä í Ĥ Ĥ Ĥ è Ç } m Ĥ Ĥ Ĥ Ĥ Ĥ b x { è ä ç ä â o f i a j q _ / 4 3 Ĥ a j _
/ - - ă a ï ã ä é } | p è } } Ü




4 - ă a ï ã ä é } | p è } } Ü



25% Exposed Steel



4 ă a ï ã ä é } | p è } } Ü



/ - - á a ã ä é } p è } } Ü	Corrosion Rate (µm/yr-1)
Minimum	0.23
Maximum	3.17
Average	1.22

50% Exposed Steel	Corrosion Rate (µm/yr-1)
Minimum	0.47
Maximum	6.35
Average	2.44

25% Exposed Steel	Corrosion Rate (µm/yr-1)
Minimum	0.94
Maximum	12.70
Average	4.88

5% Exposed Steel	Corrosion Rate (µm/yr-1)
Minimum	4.68
Maximum	63.50
Average	24.38



_ ä ç ç ä é Ĥ â o x è } é í Ĥ Ç 3 ë x ç Ĥ è Ĥ â é ä ~ é ê ç ~ x { }
} ï ã ä é } | é è } } Ü x ç } x é Ĥ
ă b ä Ü ä í Ĥ â Ĥ è Ç } m Ĥ è Ĥ â Ĥ b x { è ä ç ä â o f i a j q _ / 4 3 ă j _
/ - - á a ã ä é } | p è } } Ü

4 - á a ã ä é } | p è } } Ü



1 4 á a ã ä é } | p è } } Ü

4 á a ã ä é } | p è } } Ü

mä è} â èÉÛ j xã àmV):




_ ä ççä éÉâ â j xã Å / - - á àµm/yr):



] ç} x í Ç} ç}
| } ~ { è Éâ èÇ}
{ ä x èÉâ Å x ç}
{ ì ã } { è } |

o } éÉèÉÉî j xã ä~{äâ {ç} è} àÖΩ):



Data referring to depassivated steel (Langford and Broomfield, 1987):

> 20 kΩ cm	Low Corrosion Rate
10 - 20 kΩ cm	Low to moderate Corrosion Rate
5 - 10 kΩ cm	High Corrosion Rate
< 5 kΩ cm	Very High Corrosion Rate



Irish Hunger Memorial

Results

- ❑ The concrete area tested is at moderate risk of corrosion activity
- ❑ Presence of **Macro-cell**: as half-cell and corrosion rates were detected, it indicates that defects are present in the coating.
- ❑ As the test was conducted on a wet structure, it is anticipated that as the structure begins to dry, corrosion might accelerate.




**“L'Erection Logologique
Bleue Concrete”
Sculpture
Tarrytown, New York**

- ❑ Jean Dubuffet 1967 - 1969.
- ❑ Enameled Concrete
- ❑ Enameled Concrete, terra cotta, and steel reinforcing bars




① FRONT ELEVATION



② BACK ELEVATION



③ SIDE ELEVATION



1 CRACK ID - C3 (1 of 2)




2 CRACK ID - C5



3 CRACK ID - C1

CRACK MAPPING		
Crack ID	Width [inches]	Depth [inches]
C1	0.013	2.604
C2	0.011	0.660
C3	0.022	3.600
C3	0.006	0.840
C4	0.022	0.312
C5	0.052	0.432
C6	0.012	0.432

4 CRACK MAPPING TABLE




5 CRACK ID - C4



6 CRACK ID - C3 (2 of 2)





7 CRACK ID - C2




8 CRACK ID - C5

Ultrasonic Pulse Velocity Testing





1 BACK ELEVATION



2 SIDE ELEVATION

DUE TO THE TEXTURE AND CONFIGURATION OF THE SCULPTURE, THE FRONT SIDE WAS NOT SCANNED.




Figure 1 - Example of Rebar Data Collection





Figure 2 - Example of Rebar Data Collection

THE STEEL REINFORCEMENT WITHIN THE SCULPTURE IS CONTINUOUS AS ILLUSTRATED IN THE TABLE BELOW:

Location*	Ω [Mv]	Passed Y/N
Top Left hook -Top Right Hook	0.72 [0.15]	Yes
Top Left Hook – Base Beam	0.48 [0.10]	Yes

Table 1 Continuity Testing Results

*Drilling was limited to only few areas given the nature of the piece.




Ecorr [Potential mV] w.r.t to Ag/AgCL			
Average	Min	Max	St. Deviation
75.93	127	-76.9	46.59

Table 2 - Ecorr Statistical Analysis

Min	Max	No. of Readings	%
>	-134	27	100.00%
-134	-284	0	0.00%
<	-284	0	0.00%
		27	

Table 3 - Ecorr Statistical Analysis



Icorr [Corrosion Rate μm/yr]			
Average	Min	Max	St. Deviation
0.42	0.03	0.8	0.17
<	-284	0	0.00%
		27	

Table 4 - ICorr Statistical Analysis

Min	Max	No. of Readings	%
<	0.1	1	3.70%
0.1	1.16	26	96.30%
1.16	3.34	0	0.00%
3.34	11.6	0	0.00%
>	11.6	0	0.00%
		27	100.00%

Table 5 - ICorr Statistical Analysis



_l r oqapv l b a s a o c o a a k a] o _ e f q a _ q r o] i] o q p

“L'Erection Logologique Bleue Concrete”

Results


- ❑ THE SCULPTURE IS IN GOOD CONDITION.
- ❑ ALL REINFORCEMENT APPEARS TO BE CONTINUOUS WITHIN ITSELF.
- ❑ DURING THE FIELD WORK, **NO REBAR** WAS EXPOSED DUE TO THE NATURE OF THE OBJECT.
- ❑ DRILLING WAS LIMITED TO METAL ELEMENTS ALREADY EXPOSED SUCH AS HOOKS AND THE FOOTINGS.
- ❑ FROM THE **STABLE** CORROSION TESTING RE, MORE THAN 90% OF THE POTENTIAL DATA COLLECTED SHOWS NO SIGN OF CORROSION ACTIVITY ACCORDING TO ASTM G876 STANDARD. THE HIGHEST CORROSION RATE DETECTED IS 0.80 $\mu\text{M/YR}$ WITH AN AVERAGE OF 0.42 $\mu\text{M/YR}$ WITHIN THE TWENTY-SEVEN [27] MEASUREMENTS RECORDED.
- ❑ THE CONCRETE WAS FOUND TO BE VERY DRY WHICH DIRECTLY INFLUENCED THE POTENTIAL READINGS. AS REPORTED BY THE ROCKEFELLER FOUNDATION STAFF MEMBERS, THE SCULPTURE HAS BEEN STORED IN A WAREHOUSE FOR SEVERAL YEARS WITH LIMITED TO NO EXPOSURE TO ATMOSPHERIC CONDITION.
- ❑ AS THE SCULPTURE WAS “LOST AND THEN FOUND” NYTIMES ARTICLE [Lost and found: An 14-foot-tall Dubuffet | Rockefeller Brothers Fund](#) IT WAS DETERMINED BY THE POTANTICO CENTER, PART OF THE ROCKERFELLERS ESTATE, TO INCLUDE THE SCUPLTURE IN THE GARDEN, AMONGST THEIR 93 OTHER OUTDOOR SCULPTURES.
- ❑ A TREATMENT AND RELOCATION PLAN WAS IMPLEMENTED BY EVERGREENE ARCHITECTURAL ARTS, NOW IN ITS CURRENT LOCATION, HIGH ON HILL AT KYKUIT, ROCKERFELLER’S ESTATE IN TARRYTOWN, NY.



Hirshhorn Sculpture Garden

Washington, DC

- ❑ 1974 Gordon Bundshaft designed as part of a cohesive space for the Hirshhorn Museum
- ❑ Placed on a 1.3 acre site, with an inner sunken core with a reflection pool
- ❑ Concrete wall panels and planters of varying height and thickness
- ❑ All wall panels act as retaining walls




1 GARDEN SITE PLAN
1/16" = 1'-0"


l k p q o r q f l k q v m l i l c v

e f o p e e l o k






1 WEST ELEVATION - SPR SCAN LOCATIONS
NTS



3 SPR SCAN #29 OF VERTICAL REBAR
NTS












6 SPR SCAN #36 OF HORIZONTAL REBAR
NTS


7 SECTION B-B
NTS



4 ELEVATION ISOMETRIC VIEW (TYP.)








1 SOUTH ELEVATION - CORROSION POTENTIALS (i-VOS)
3/16" = 1'-0"




5 NORTH ELEVATION - CORROSION POTENTIALS (i-VOS)
3/16" = 1'-0"



8 SOUTH ELEVATION - CORROSION RATES (i-COS)
3/16" = 1'-0"




12 NORTH ELEVATION - CORROSION RATES (i-COS)
3/16" = 1'-0"




15 SOUTH ELEVATION - RESISTIVITY (i-ROM)
3/16" = 1'-0"



19 NORTH ELEVATION - RESISTIVITY (i-ROM)
3/16" = 1'-0"





Hirschhorn Sculpture Garden Walls

Results



- ❑ ASR affected concrete
- ❑ High Moisture driving corrosion




Tibbetts Park Pavilion

Yonkers, NY



- ❑ **1920s Lakeside Pavilion and Bandstand**
- ❑ **One of the first developed parks in Westchester, NY with 161 acres**
- ❑ **Pavilion / gazebo was constructed for the park opening**
- ❑ **Site was largely abandoned and was in a very deteriorated state**
- ❑ **No existing drawings or construction information was available**




_fo_r j baoakqf] i p_] k








NORTH COLUMN





] il kc qe a iak c qe p_] k















Likely ASR related issues



Delamination spalling issues



_l k_oaqa p]j mi a bol j
r mmaođ as ai




• j äçèxç {ä lä ç É ~çä à
ã lä ÖÉÇ Åçxî èä Åçxî ÉÇ
ã lä Ö





- Comprise of historic **Portland cement** and **dolomitic marble** with ratio of **1:3.25**
- NO evidence of ASR
- Cracking occurred most likely due to **freeze and thawing cycles.**

• _çx {Öé í ÉÇ {xÜÉà
{xçz ä â xè} | } ã ä éÉä â




Plane Polarized Light


• _xçz ä â xè} | ã xéè}
xlä â Å èÇ} éêçx {} ä ~
èÇ} éxà ã Ü



_l k_oaqa p]j mi a bol j
{äâ {ç} è}



- mxéè} {ä lä ç Åçxî ÉÇ
ä çxâ ÅÉÇ
- j É çxèä ä~_ Ĥ ð
/Ĥ Ĥ 4
- k l }ëĤ }â {} ä~] p o
- _ xçz äâ xè} | í ÉÇ
| }â é} {xÜÉà
{xçz äâ xè}





TIBBETTS PARK PAVLION

Results

- ❑ Freeze Thaw affected concrete
- ❑ High Moisture
- ❑ Significant Delaminations

br qr oa _ e] i i a k c a p





p a p p f l k a s] i r] q f l k

Resources

Evaluate this Session



To complete the session evaluation, open the ICRI Convention App.

Under **Plan Your Event**, select Schedule, and then the Technical Session you are attending. Select the sub-session you are attending, scroll down to Resources, and select Evaluate this Session.

] k v n r a p q f l k p ê